

EOBD Sprinter High Roof

2012

License Plate Number:VIN: WD3PE8CB9C5700564

Vehicle Software Version: V23.12Diagnostic Software Version: V2.28

Test Result

Tested 1 system(s), 11 fault code(s) in total

Vehicle body systemFault(11) ▾

1. Lost Communication With TCM

2. Particulate Filter Restriction - Soot Accumulation Bank 1

3. Intake Manifold Runner Control Stuck Closed Bank 1A

4. Intake Manifold Runner Control Stuck Closed Bank 2A

5. Manifold Absolute Pressure/Barometric Pressure Circuit Low

6. Mass Or Volume Air Flow A Circuit Low

7. Mass Or Volume Air Flow A Circuit

8. Intake Air Temperature Sensor 1 Circuit Low Bank 1

9. Catalyst Temperature Sensor Circuit High Bank 1 Sensor 2

10. Lost Communication With NOx Sensor A

11. Intake Manifold Runner Control Stuck Open Bank 1A

Professional Diagnostic Report

EOBDAbnormal(11) ▾

Fault Code(11)

Fault Code	Description	Status
U0101	Lost Communication With TCM	Current

Fault Code	Description	Status
P2463	Particulate Filter Restriction - Soot Accumulation Bank 1	Current
P2006	Intake Manifold Runner Control Stuck Closed Bank 1A	Current
P2007	Intake Manifold Runner Control Stuck Closed Bank 2A	Current
P0107	Manifold Absolute Pressure/Barometric Pressure Circuit Low	Current
P0102	Mass Or Volume Air Flow A Circuit Low	Current
P0100	Mass Or Volume Air Flow A Circuit	Current
P0112	Intake Air Temperature Sensor 1 Circuit Low Bank 1	Current
P042D	Catalyst Temperature Sensor Circuit High Bank 1 Sensor 2	Current
U029D	Lost Communication With NOx Sensor A	Current
P2004	Intake Manifold Runner Control Stuck Open Bank 1A	Current

Disclaimer

This diagnostic report is provided for reference only for vehicle inspection and repair. The vehicle operation data provided in this report are static data. Detailed dynamic diagnostic data can be read using professional repair equipment. LAUNCH shall not be liable for any accidents and failures arising therefrom!