

Subaru XV CrossTrek Prm+AWP

2014

License Plate Number:VIN: JF2GPACCXE8277965

Vehicle Software Version: V26.41Diagnostic Software Version: V2.28

Test Result

Tested 1 system(s), 6 fault code(s) in total

Vehicle body systemFault(6) ▾

1. VDC Interruption For Engine Convenience

2. AT

3. Cylinder 1 Misfire Detected

4. Cylinder 1 Misfire Detected

5. Preparatory Codes

6. Preparatory Codes

The following systems tested normal

Vehicle body systemNormal >

Professional Diagnostic Report

Anti-lock Braking System(ABS)Abnormal(2) ▾

Fault Code(2)

Fault Code	Description	Status
C1422	VDC Interruption For Engine Convenience	The past
C1431	AT	The past

EOBD

Abnormal(1) ▼

Fault Code(1)

Fault Code	Description	Status
P0301	Cylinder 1 Misfire Detected	Pending

Transmission Control Module(TCM)

Normal

Engine Control Module(ECM)

Abnormal(3) ▼

Fault Code(3)

Fault Code	Description	Status
P0301	Cylinder 1 Misfire Detected	
20B11	Preparatory Codes	
20B01	Preparatory Codes	

Supplemental Inflatable Restraint System(SRS)

Normal

Disclaimer

This diagnostic report is provided for reference only for vehicle inspection and repair. The vehicle operation data provided in this report are static data. Detailed dynamic diagnostic data can be read using professional repair equipment. LAUNCH shall not be liable for any accidents and failures arising therefrom!