

Vehicle Test Report (VTR)

LAUNCH

Report No.: D0113755824

Diagnostic Time: 2026-08-31 14:33:05

Report Type: 1

SUBARU Forester Premium AWP

2011

License Plate Number:

VIN: JF2SHADCXBG780001

Vehicle Software Version: V26.41

Diagnostic Software Version: V2.28

Test Result

Tested 1 system(s), 9 fault code(s) in total

Vehicle body system	Fault(9) ▾
1. Cylinder 1 Misfire Detected 2. Cylinder 3 Misfire Detected 3. Improper CAN Communication 4. VDC control interruption because of engine instructions 5. Steering Angle Sensor malfunction 6. Cylinder 3 Misfire Detected 7. Cylinder 1 Misfire Detected 8. Preparatory Codes 9. Preparatory Codes	

The following systems tested normal

Vehicle body system	Normal >
---------------------	----------

Professional Diagnostic Report

Supplemental Inflatable Restraint System(SRS)	Normal
EOBD	Abnormal(2) ▾
Fault Code(2)	

Fault Code	Description	Status
P0301	Cylinder 1 Misfire Detected	Pending
P0303	Cylinder 3 Misfire Detected	Pending

Anti-lock Braking System(ABS)**Abnormal(3)** ∨**Fault Code(3)**

Fault Code	Description	Status
C0047	Improper CAN Communication	
C0057	VDC control interruption because of engine instructions	
C0071	Steering Angle Sensor malfunction	

Engine Control Module(ECM)**Abnormal(4)** ∨**Fault Code(4)**

Fault Code	Description	Status
P0303	Cylinder 3 Misfire Detected	
P0301	Cylinder 1 Misfire Detected	
20B11	Preparatory Codes	
20B01	Preparatory Codes	

Disclaimer

This diagnostic report is provided for reference only for vehicle inspection and repair. The vehicle operation data provided in this report are static data. Detailed dynamic diagnostic data can be read using professional repair equipment. LAUNCH shall not be liable for any accidents and failures arising therefrom!