

EOBD Sprinter High

2014

License Plate Number:VIN: WD3PE8CCXE5860139

Vehicle Software Version: V23.12Diagnostic Software Version: V2.28

Test Result

Tested 1 system(s), 5 fault code(s) in total

Vehicle body system

Fault(5) ▾

1. NOx Sensor Circuit Range/Performance Bank 1 Sensor 2

2. Cylinder 6 Misfire Detected

3. Cylinder 1 Misfire Detected

4. Random/Multiple Cylinder Misfire Detected

5. ECM/PCM Engine Off Timer Performance

Professional Diagnostic Report

EOBD

Abnormal(5) ▾

Fault Code(5)

Fault Code	Description	Status
P229F	NOx Sensor Circuit Range/Performance Bank 1 Sensor 2	Current
P0306	Cylinder 6 Misfire Detected	Current
P0301	Cylinder 1 Misfire Detected	Current
P0300	Random/Multiple Cylinder Misfire Detected	Current

Fault Code	Description	Status
P2610	ECM/PCM Engine Off Timer Performance	Pending

Disclaimer

This diagnostic report is provided for reference only for vehicle inspection and repair. The vehicle operation data provided in this report are static data. Detailed dynamic diagnostic data can be read using professional repair equipment. LAUNCH shall not be liable for any accidents and failures arising therefrom!