

Chevrolet Express

2019

License Plate Number:VIN: 1GCZGGFG4K1289753

Vehicle Software Version: V50.30Diagnostic Software Version: V2.28

Test Result

Tested 2 system(s), 7 fault code(s) in total

Power system

Fault(7) ▾

1. Fuel Pump Control Module Requested Malfunction Indicator Lamp (MIL) Illumination

2. Transmission Control Module Requested Malfunction Indicator Lamp (MIL) Illumination

3. Lost Communication with Fuel Pump Control Module

4. Lost Communication with Electronic Brake Control Module

5. Lost Communication with Body Control Module

6. Ignition On/Start Switch Circuit High Voltage

7. Lost Communication with Electronic Brake Control Module

The following systems tested normal

Safety and Security system

Normal >

Professional Diagnostic Report

Engine Control Module (ECM)

Abnormal(5) ▾

Fault Code(5)

Fault Code	Description	Status
P069E-00	Fuel Pump Control Module Requested Malfunction Indicator Lamp (MIL)	Current

Fault Code	Description	Status
	Illumination	
P0700-00	Transmission Control Module Requested Malfunction Indicator Lamp (MIL) Illumination	Current
U0109-00	Lost Communication with Fuel Pump Control Module	Current
U0121-00	Lost Communication with Electronic Brake Control Module	Current
U0140-00	Lost Communication with Body Control Module	Passed And Failed

Inflatable Restraint Sensing And Diagnostic Module (IRSDM)	Normal
Transmission Control Module (TCM)	Abnormal(2) ▾

Fault Code(2)		
Fault Code	Description	Status
P2535-00	Ignition On/Start Switch Circuit High Voltage	Passed And Failed
U0121-00	Lost Communication with Electronic Brake Control Module	Current

Disclaimer

This diagnostic report is provided for reference only for vehicle inspection and repair. The vehicle operation data provided in this report are static data. Detailed dynamic diagnostic data can be read using professional repair equipment. LAUNCH shall not be liable for any accidents and failures arising therefrom!