

EOBD

N/A

License Plate Number:VIN: 3C6TRVDG6JE107867

Vehicle Software Version: V23.12Diagnostic Software Version: V2.28

Test Result

Tested 1 system(s), 4 fault code(s) in total

Vehicle body systemFault(4) ▾

1. Cylinder 3 Misfire Detected

2. Engine Oil Temperature Sensor A Circuit Low

3. Bank 1 Air-Fuel Ratio Imbalance

4. Transmission Fluid Pressure Sensor/Switch H Circuit Range/Performance

Professional Diagnostic Report

EOBDAbnormal(4) ▾

Fault Code(4)

Fault Code	Description	Status
P0303	Cylinder 3 Misfire Detected	Current
P0197	Engine Oil Temperature Sensor A Circuit Low	Current
P219A	Bank 1 Air-Fuel Ratio Imbalance	Current
P084B	Transmission Fluid Pressure Sensor/Switch H Circuit Range/Performance	Current

Disclaimer

This diagnostic report is provided for reference only for vehicle inspection and repair. The vehicle operation data provided in this report are static data. Detailed dynamic diagnostic data can be read using professional repair equipment. LAUNCH shall not be liable for any accidents and failures arising therefrom!