

Vehicle Test Report (VTR)

LAUNCH

Report No.: D0113762725

Diagnostic Time: 2026-08-31 15:57:20

Report Type: 1

EOBD NRR

2016

License Plate Number:

VIN: JALE5W16XG7303462

Vehicle Software Version: V23.12

Diagnostic Software Version: V2.28

Test Result

Tested 1 system(s), 6 fault code(s) in total

Vehicle body system

Fault(6) ▾

1. Turbocharger/Supercharger Boost Control Solenoid A Circuit/Open

2. Turbocharger Boost Control Position Sensor A Circuit Range/Performance

3. EGR Sensor A Circuit Range/Performance

4. Cylinder 3 Misfire Detected

5. Cylinder 3 Fuel Injector A Offset Learning At Min Limit

6. Reductant Metering Unit Temperature Sensor Circuit Range/Performance

Professional Diagnostic Report

EOBD

Abnormal(6) ▾

Fault Code(6)

Fault Code	Description	Status
P0045	Turbocharger/Supercharger Boost Control Solenoid A Circuit/Open	Current
P2563	Turbocharger Boost Control Position Sensor A Circuit Range/Performance	Current
P046C	EGR Sensor A Circuit Range/Performance	Current

Fault Code	Description	Status
P0303	Cylinder 3 Misfire Detected	Pending
P02D0	Cylinder 3 Fuel Injector A Offset Learning At Min Limit	Pending
P20AD	Reductant Metering Unit Temperature Sensor Circuit Range/Performance	Permanent

Disclaimer

This diagnostic report is provided for reference only for vehicle inspection and repair. The vehicle operation data provided in this report are static data. Detailed dynamic diagnostic data can be read using professional repair equipment. LAUNCH shall not be liable for any accidents and failures arising therefrom!